

# TORCTOOL

## TOOL MODEL: TTZ-2 W/ HEX LINK (SIZES #1-#6) PRESSURE/TORQUE CONVERSION CHART

### Standard Torque Chart

PRESSURE IN PSI	FT. LBS.	TORQUE IN		PRESSURE IN BAR
		KGM	NM	
1500	259	36	351	104
1600	277	38	376	110
1800	314	43	426	124
2000	351	49	475	138
2200	387	54	525	152
2400	423	59	574	165
2600	460	64	623	179
2800	496	69	672	193
3000	532	74	722	207
3200	568	79	770	220
3400	604	84	819	234
3600	640	88	867	248
3800	676	93	916	262
4000	711	98	964	276
4200	748	103	1014	290
4400	785	109	1064	303
4600	821	114	1113	317
4800	858	119	1163	331
5000	895	124	1213	345
5200	931	129	1262	358
5400	968	134	1312	372
5600	1004	139	1361	386
5800	1041	144	1411	400
6000	1077	149	1460	414
6200	1114	154	1510	427
6400	1150	159	1559	441
6600	1186	164	1608	455
6800	1223	169	1658	468
7000	1259	174	1707	482
7200	1296	179	1757	496
7400	1332	184	1806	510
7600	1369	189	1856	524
7800	1405	194	1905	538
8000	1442	199	1955	552
8200	1478	204	2004	565
8400	1515	209	2053	579
8600	1551	215	2103	593
8800	1588	220	2152	607
9000	1624	225	2202	620
9200	1661	230	2251	634
9400	1697	235	2301	648
9600	1734	240	2351	662
9800	1771	245	2400	676
10000	1807	250	2450	690